

YEAR MONTH DAY

070621

WinView Alarm Log File (c) 1995 Rockwell Software Inc.

What happened	Where	Fix or Release	Where	Time	Time	Code	Event
IN ALARM - 06/21/07	-Sec. 1 Home Position	PX 1		02:48:34PM		100	Event 1
OUT ALARM - 06/21/07	Sec. 1 Home Position	PX 1		02:48:34PM	02:51:01PM	100	
IN ALARM - 06/21/07	Sec. 4 Home Position	PX 1		02:51:04PM		280	Event 2
OUT ALARM - 06/21/07	Sec. 4 Home Position	PX 1		02:51:04PM	02:51:08PM	280	
IN ALARM - 06/21/07	E Stop Operators Panel			04:55:14PM		20	Event 3
OUT ALARM - 06/21/07	E Stop Operators Panel			04:55:14PM	05:05:19PM	20	(INCIDENT)
IN ALARM - 06/21/07	Sec. 1 overspeed			05:10:44PM		48	Event 4
OUT ALARM - 06/21/07	Sec. 1 overspeed			05:10:44PM	09:26:17PM	48	
IN ALARM - 06/21/07	Pressure Error PS 1			09:26:17PM		40	Event 5
OUT ALARM - 06/21/07	Pressure Error PS 1			09:26:17PM	09:35:10PM	40	
IN ALARM - 06/21/07	Sec. 5 Hydraulic	PX 4 - PX 15		09:38:02PM		346	Event 6

When E-STOP Was Hit

Where E-Stop was hit

When E-Stop was released