

070621

WinView Alarm Log File (c) 1995 Rockwell Software Inc.

| | | | |
|------------------------|--------------|------------|-----|
| IN ALARM - 06/21/07 | 02:48:34PM | | 100 |
| Sec. 1 Home Position | PX 1 | | |
| OUT ALARM - 06/21/07 | 02:48:34PM | 02:51:01PM | 100 |
| Sec. 1 Home Position | PX 1 | | |
| IN ALARM - 06/21/07 | 02:51:04PM | | 280 |
| Sec. 4 Home Position | PX 1 | | |
| OUT ALARM - 06/21/07 | 02:51:04PM | 02:51:08PM | 280 |
| Sec. 4 Home Position | PX 1 | | |
| IN ALARM - 06/21/07 | 04:55:14PM | | 20 |
| E Stop Operators Panel | | | |
| OUT ALARM - 06/21/07 | 04:55:14PM | 05:05:19PM | 20 |
| E Stop Operators Panel | | | |
| IN ALARM - 06/21/07 | 05:10:44PM | | 48 |
| Sec. 1 Overspeed | | | |
| OUT ALARM - 06/21/07 | 05:10:44PM | 09:26:17PM | 48 |
| Sec. 1 Overspeed | | | |
| IN ALARM - 06/21/07 | 09:26:17PM | | 40 |
| Pressure Error PS 1 | | | |
| OUT ALARM - 06/21/07 | 09:26:17PM | 09:35:10PM | 40 |
| Pressure Error PS 1 | | | |
| IN ALARM - 06/21/07 | 09:38:02PM | | 346 |
| Sec. 5 Hydraulic | PX 4 - PX 15 | | |