

6-22-27 Superman Cable Measurement

Cable for End

0-10 ft .432 = 10.9 mi

~~11-20ft~~ 11.0

21-30 11.0

31-~~40~~ 40 11.0

41-50 11.0

51-60 11.0

61-70 10.9

71-80 11.0

81-90 11.0

91-100 11.0

101-110 10.9

111-120 10.8

~~121-130~~

125 11.3

135 11.3

135

See Permanent Gauge  
Assumed cable loss

Sins of broken strand.  
125 new sins of broken strand

Cables Cuesist

~~135~~ Brake

137.5 - 11.3

140 11.0

142.5 - 11.8

145 10.8

147.5 10.9

150 10.8

152.5 10.8

155 10.6

160 10.8

170 11.0

180 11.0

195 - 11.0

200 11.0

210 11.0

230 11.1

250 11.0

135-150 Abraded cable

Sins Cable

27.3 measurement

~~27.3~~  
Sufford to b. 27.5